

To: X3T13 membership
From: Pete McLean
Date: 29 February 1996
Subj: Editorial errors in ATA-3

While working on the 1153 document, I discovered a couple of editorial errors that remain in thw ATA-3 document. It would be nice to fix these when the letter ballot comment resolution is done in creating D2008-R7.

1. In subclauses 6.2.1 and 6.2.2, the register address is DA(2:1). This should be DA(2:0) as is shown for all the other registers.
2. In ATA-2 the definition of the BBK error was removed and bit 7 of the Error register was defined as reserved. BBK was never removed from the tables showing valid error bits for commands. All references to BBK should be removed.