

ACS-2 Issues List

Rev 7
January 21, 2009

Line	#	Issue	Owner	Status	Date
1	1	Define a log address for IDENTIFY DEVICE data expansion	Stevens	Open	16-Aug-07
2	2	In 7.18.6.17 IDENTIFY PACKET DEVICE data word 62 DMADIR bit definitions are not even close to that in the table. Carried over from e06122 issue #72	Overby	Open	3-Mar-06
3	3	Should we add a discussion on what enabled means (related to supported definition)? Should this be in IDENTIFY DEVICE or in 4.1 (Overview)? Carried over from e06122 issue #99	Overby	Open	21-Jun-06
4	4	Incorporate e06162 - Simulated Delay Event Carried over from e06122 issue #168 (had to correct document number from e05162 to e06162) Possible ACS-3	Chen	Open	26-Oct-06
5	5	In DCO SET word 3-6, there is no protection for security enabled. Resolution: Add "The device may abort DCO SET to change words 3-6 if security is enabled." Carried over from e06122 issue #190	Hatfield	Rejected	16-Dec-08
6	6	In the power-up in standby feature set, paragraph 3 indicates that you can not exit the standby state until a SET FEATURES spin-up command is received when PUIS is enabled. This is not reflected in the state transition diagram for power management, possibly because we do not have a tendency to document error transitions. Carried over from e06122 issue #192 See e08142 for a resolution.	Hatfield	Open	24-Apr-07
7	7	Incorporate e07159, change Host Vendor Specific to Scratch-pad. The name of the Host Vendor Specific log pages has lead to quite a bit of confusion by host vendors. They look at the name and assume they can define how these logs work. I would like to change the names as follows: Host Vendor Specific log -> Scratch-pad logs Device Vendor Specific log -> Vendor Specific Carried over from e06122 issue #197 Could delay to ACS-3	Stevens	Open	23-May-07

Line	#	Issue	Owner	Status	Date
8	8	Incorporate e07154r6, Data Set Management Opcode = 06h IDENTIFY DEVICE data word 169 Bits 15:1 - Reserved Bit 0 - Trim function is supported DCO Set/Identify data word 21 bit 10	Stevens	Done	22-Oct-08
9	9	Incorporate e06180r10, Additional device statistics - Usage Length Merge with log address 04 Page 03h	Stevens	Done	17-Dec-08
10	10	Incorporate e06181r12 , Additional device statistics – Errors	Stevens	Done	17-Dec-2008
11	11	Incorporate e06182r8, Additional device statistics – Free Fall Assigned to Log Address 04h page 02h	Stevens	Done	16-Dec-08
12	12	Incorporate e06183r11, Additional device statistics – Temperature Assigned to Log Address 04h page 05h	Stevens	Done	18-Dec-08
13	13	Incorporate e06184r7, Additional device statistics – Solid State Media / NV Cache Assigned to Log Address 04h page 02h	Chen	Open	25-Oct-06
14	14	External Path Protection (e07162)	Stevens	Rejected	14-Sep-07
15	15	Incorporate e06174, SCT Capabilities (action codes) Could delay to ACS-3	Wolford	Open	
16	16	Incorporate e06161, Reporting Device Footprint Proposal integrated into ATA8-ACS and is automatically brought forward.	Bellamy	Rejected	17-Apr-08
17	17	Was a duplicate of issue #4			
18	18	Incorporate e07123r4, REQUEST SENSE for ATA Assigned Resources: Opcode: 0Bh IDENTIFY DEVICE data Word 119 bit 6 - Supported Word 120 bit 6 - Enabled SET FEATURES subcommand C3h	Stevens	Done	22-Oct-08
19	19	Incorporate e07104, Security Command Update	Chen	Open	28-Nov-06
20	20	Incorporate e07134, Remove Input/Output Structures Removed from agenda	Bellamy	Rejected	17-Apr-08
21	21	Incorporate e05142, Proactive Reporting and Correcting Removed from agenda	Shu	Rejected	17-Apr-08
22	22	Incorporate e07121, Set Features Set Profile	Hatfield	Open	1-Feb-07

Line	#	Issue	Owner	Status	Date
23	23	Incorporate e07153, SSD Identify Could be delayed until ACS-3	Shu	Rejected	16-Dec-08
24	24	Add list of acronyms (e08128)	Stevens	Done	16-Dec-08
25	25	Add IDENTIFY DEVICE data table cross references to text	Stevens	Done	21-Jan-09
26	26	Remove ATAPI and place it in its own standard Could be delayed ACS-3	Stevens	Open	17-Apr-08
27	27	Incorporate e07189, Extended Security Could be delayed until ACS-3	Chen	Open	22-Oct-07
28	28	Incorporate e07188, Sanitize Command	Geldman	Open	21-Apr-07
29	29	Incorporate e08108r1, CFAST IDENTIFY DEVICE data Assigned IDENTIFY DEVICE data word 69 bit 15 to this proposal New word is titled: Additional Supported (Needs Work)	Stevens	Done	16-Dec-08
30	30	Incorporate e08106r10, Device Statistics overview	Stevens	Done	22-Oct-08
31	31	Incorporate e07169, SCT Zone Control Could be delayed until ACS-3	Colegrove	Open	6-Aug-07
32	32	For commands which have an error return specified as "LBA of first unrecoverable error" we do not address the following: a) There is no statement about the condition of the sectors following the error. We should probably state somewhere that the contents of the remaining sectors for a write command are unknown. b) There needs to be a statement somewhere that "LBA of the first unrecoverable error" refers to the first error found by the device and has nothing to do with the sequence of data retrieval or writing. The device could begin writing sectors from the end of the command and move forward to the beginning... We probably need to add something to the subclause on errors...	Stevens	Open	17-Apr-08
33	33	Incorporate e07168r11, Transport Device Statistics Assigned to Log Address 04h page 06h	Stevens	Done	18-Dec-08
34	34	Replace the dash in range specifications with ".."	Stevens	Done	22-Oct-08
35	35	Incorporate e08140 - For DCO SET, does an error leave IDENTIFY DEVICE data intact	Hatfield	Open	23-Apr-08
36	36	Incorporate e08140 - For DCO SET, can it ignore requests for changeable fields that it can not honor	Hatfield	Open	23-Apr-08
37	37	For the GPL commands, we need to report which page failed	Stevens	Open	23-Apr-08
38	38	Incorporate e08129r2, New DMA commands	Stevens	Done	21-Jan-09

Line	#	Issue	Owner	Status	Date
39	39	Revisit the funny status for REQUEST SENSE- Use a status bit instead of a signature	Stevens	Open	23-Apr-08
40	40	Incorporate e08xxx, check condition for SMART status	Overby	Open	23-Apr-08
41	41	e08155 - Recommend ASC/ASCQ for all error bits	Overby	Open	23-Apr-08
42	42	Incorporate e08154 - Make numeric separators closer to ISO compliance Resolution In decimal numbers, use spaces to separate groups of 3 digits and "." as the decimal point.	Martin	Open	23-Apr-08
43	43	Add a new status byte for HPA to report the current mode Could be delayed to ACS-3	Colegrove	Open	24-Jun-08
44	44	Incorporate e08116, report non-volatile write cache	Livaccari	Open	26-Feb-08
45	45	Incorporate e08120, extended power conditions	Hatfield	Open	10-Jun-08
46	46	Incorporate e08152 - Obsolete the TCQ feature set	Overby	Open	24-Jun-08
47	47	Remove the phrase "task file" from annex D.3.2 Incorporated into ACS.	Stevens	Rejected	24-Jun-08
48	48	Revisit list of alignments in E.4.3	Elloitt	Open	24-Jun-08
49	49	Incorporate e08121r1, long physical sector diagnostics	Stevens	Done	18-Dec-08
50	50	Incorporate e08122, 2 minor fixes to ACS-2	Stevens	Done	22-Oct-08
51	51	The following description is added to ATA-8 revision.6. "7.41 SECURITY DISABLE PASSWORD If security is disabled, then: a) if the Identifier bit is set to User, then the device shall return command aborted; or b) if the Identifier bit is set to Master, then the device may compare the password supplied with the stored Master password." But the above description is added to only SECURITY DISABLE command. We request that the same description is added to SECURITY UNLOCK and SECURITY ERASE UNIT commands too. Can we pls add this to the comment list for ACS	Puri	Open	24-Jun-08
52	52	Incorporate e08130r1, OEM ID String	Stevens	Done	21-Oct-08
53	53	Incorporate e08126, Request for the reservation or assignment of Security Protocol value for TrustedFlash	Shternhell	Open	25-Jun-08
54	54	Incorporate e08143 - Updates from SATA 2.6. Material includes PRIO bit and IDLE IMMEDIATE UNLOAD info.	Hatfield	Open	21-Aug-08

Line	#	Issue	Owner	Status	Date
55	55	In the SMART ENABLE/DISABLE ATTRIBUTE AUTOSAVE description, the first sentence reads "This command enables and disables the optional attribute autosave feature of the device." This is in conflict with the statement in the Feature Set which states: "This 28-bit command is mandatory for devices that implement the SMART feature set"	Hatfield	Rejected	16-Dec-08
56	56	7.53.6.12 Self-test routine recommended polling time ---- Indicate that this section applies to all of these: - short self-test recommended polling time - extended self-test recommended polling time - conveyance test recommended polling time	Stevens	Open	21-Aug-08
57	57	Incorporate e08127r3, Time in over/Under Temperature	Stevens	Done	18-Aug-08
58	58	Incorporate e08135, Alternative Solid State Media Statistics	Hatfield	Open	21-Oct-08
59	59	Incorporate e08137r4, DRAT	Stevens	Done	18-Dec-08
60	60	The Read PIO Error (Table 134) and Read DMA Error (Table 130) as the same and can be merged.	Stevens	Done	16-Dec-08
61	61	Add "SCT Read Long" to the definition of read commands.	Stevens	Done	23-Oct-08
62	62	Incorporate e08154r0 - Do we need a description for our new ".." range operator.	Stevens	Done	21-Jan-09
63	63	Define User Data "Data that is transferred between the application client and the device using read commands and write commands."	Stevens	Done	16-Dec-08
64	64	Reverting to power on defaults changed in ATA8-ACS and needs to be reviewed.	Colegrove	Open	16-Dec-08
65	65	Incorporate e08148 - Reservations for iVDR	Hatfield	Open	16-Dec-08
66	66	Incorporate e08145 - Errata for ATA8-ACS	Hatfield	Open	16-Dec-08
67	67	Incorporate e08151 - Device Alerts Log	Geldman	Open	16-Dec-08
68	68	Incorporate e08146 - Maximum LBA Range Support	Wells	Open	16-Dec-08
69	69	Incorporate e08153 - Obsolete SCT Read Long	Hatfield	Open	16-Dec-08
70	70	Define User Data Area Any area of the media where user data may be stored.	Stevens	Open	16-Dec-08
71	71				
72	72				
73	73				
74	74				
75	75				
76	76				
77	77				

Line	#	Issue	Owner	Status	Date
78	78				
79	79				
80	80				
81	81				
82	82				
83	83				
84	84				
85	85				
86	86				
87	87				
88	88				
89	89				
90	90				
91	91				
92	92				
93	93				
94	94				
95	95				
96	96				
97	97				
98	98				
99	99				
100	100				
101	101				
102	102				
103	103				
104	104				
105	105				
106	106				
107	107				
108	108				
109	109				
110	110				
111	111				

Line	#	Issue	Owner	Status	Date
112	112				
113	113				
114	114				
115	115				
116	116				
117	117				
118	118				
119	119				
120	120				
121	121				
122	122				
123	123				
124	124				
125	125				
126	126				
127	127				
128	128				
129	129				
130	130				
131	131				
132	132				
133	133				
134	134				
135	135				
136	136				
137	137				
138	138				
139	139				
140	140				
141	141				
142	142				
143	143				
144	144				
145	145				

Line	#	Issue	Owner	Status	Date
146	146				
147	147				
148	148				
149	149				
150	150				
151	151				
152	152				
153	153				
154	154				
155	155				
156	156				
157	157				
158	158				
159	159				
160	160				
161	161				
162	162				
163	163				
164	164				
165	165				
166	166				
167	167				
168	168				
169	169				
170	170				
171	171				
172	172				
173	173				
174	174				
175	175				
176	176				
177	177				
178	178				
179	179				

Line	#	Issue	Owner	Status	Date
180	180				
181	181				
182	182				
183	183				
184	184				
185	185				
186	186				
187	187				
188	188				
189	189				
190	190				
191	191				
192	192				
193	193				
194	194				
195	195				
196	196				
197	197				
198	198				
199	199				
200	200				
201	201				
202	202				
203	203				
204	204				
205	205				
206	206				
207	207				
208	208				
209	209				